



- |                                                     |                                                 |                                                        |                                                    |
|-----------------------------------------------------|-------------------------------------------------|--------------------------------------------------------|----------------------------------------------------|
| 1. Independence Rd MP 3.17 Culvert Replacement      | 15. Wendling Rd MP 0.106 Culvert Replacement    | 29. Holcomb Rd MP 0.819 Culvert Replacement            | 43. 35 Program - Pigeon Springs Rd MP 0.00-2.538   |
| 2. Harris Rd MP 0.06 Culvert Replacement            | 16. Lost Valley Rd MP 1.657 Culvert Replacement | 30. Borovec Rd MP 0.032 Culvert Replacement            | 44. Magnus Rd MP 0.541 Culvert Replacement         |
| 3. Harris Rd MP 0.27 Culvert Replacement            | 17. King Rd MP 12.26 Bridge Scour               | 31. Bishop Rd MP 2.839 Culvert Replacement             | 45. Johnson Rd MP 0.492 Culvert Replacement        |
| 4. Harris Rd MP 1.49 Culvert Replacement            | 18. King Rd MP 11.57 Culvert Replacement        | 32. Newaukum Valley Rd MP 2.336 Culvert Replacement    | 46. Pleasant Valley Rd MP 1.50 Culvert Replacement |
| 5. Garrard Creek Road Long Term Scour Protection    | 19. Wildwood Rd MP 10.14 Bridge Scour           | 33. Rush Rd MP 1.315 Culvert Replacement               | 47. Davison Road MP 0.01 Bridge Rehabilitation     |
| 6. Manners Rd MP 1.54 Culvert Replacement           | 20. Wildwood Rd MP 8.54 Culvert Replacement     | 34. Jackson Hwy S MP 0.639 Culvert Replacement         | 48. Mienars Rd MP 0.108 Culvert Replacement        |
| 7. Harrison Avenue Improvements                     | 21. Wildwood Rd MP 7.88 Culvert Replacement     | 35. Toledo Salmon Creek Rd MP 1.20 Culvert Replacement | 49. SR 508 MP 31.82 Culvert Replacement            |
| 8. Ingalls Rd MP 0.108 Bridge Replacement           | 22. Wildwood Road Slide Repair                  | 36. 3R Program - Howe Rd MP 0.00-3.315                 | 50. Sewer Plant Rd MP 0.13 Culvert Replacement     |
| 9. Bunker Creek Rd MP 2.681 Culvert Replacement     | 23. Olequa Dr MP 0.378 Culvert Replacement      | 37. 3R Program - Classe Rd MP 0.00-2.117               | 51. Davis Lake Rd MP 1.345 Culvert Replacement     |
| 10. Elk Creek Rd MP 0.405 Culvert Replacement       | 24. Telegraph Rd MP 0.778 Bridge Replacement    | 38. Spencer Rd MP 5.38 Bridge Replacement              | 52. Cline Rd MP 4.15 Culvert Replacement           |
| 11. Harkum Rd MP 0.802 Culvert Replacement          | 25. 3R Program - Ferrier Rd MP 0.721 to 3.791   | 39. Spencer Rd MP 3.53 Culvert Replacement             | 53. Cline Rd MP 6.384 Culvert Replacement          |
| 12. Harkum Rd MP 0.872 Culvert Replacement          | 26. Sargent Rd MP 1.33 Bridge Scour             | 40. Senn MP 0.89 Bridge Scour                          | 54. Cline Rd MP 9.17 Culvert Replacement           |
| 13. Pe Ell McDonald Rd MP 4.032 Culvert Replacement | 27. Haywire Rd MP 2.55 Culvert Replacement      | 41. Lucas Creek Rd MP 4.24 Culvert Replacement         |                                                    |
| 14. Pe Ell McDonald Rd MP 4.778 Culvert Replacement | 28. Haywire Rd MP 2.40 Culvert Replacement      | 42. Lucas Creek Rd MP 4.39 Culvert Replacement         |                                                    |



**Figure 1: Vicinity Map**  
2023 Wetland RFP